Содержание

1

The reason for the subscriber's permanent redirection to the notification page is the following: DPI does not see the redirection to the www-site with the notification, so it does not reset the service state. In order to make the reset occurs automatically traffic to the www-server have to be routed through the DPI.