Содержание

Framed route 3
framed route show 3
framed route clear 3
framed route delete 3

Framed route

Framed-Route L2 BRAS routes management commands. Routes are stored in fastDPI UDR.

framed route show

View all routes:

```
fdpi_cli -r <address> framed route show
```

framed route clear

Removing all routes entries from the UDR:

```
fdpi_cli -r <address> framed route clear
```

framed route delete

Removing the specified route. The command argument is the subnet:

```
# removing an IPv4-subnet
fdpi_cli -r <address> framed route delete 10.20.30.0/24

# removing an IPv6-subnet
fdpi_cli -r <address> framed route delete 2001:5006:34ff::/60
```