Table of Contents

10 Additional DPI FAQ

1.How the load is distributed across processor cores (12 cores/2 cluster)?

```
The cores are distributed between different tasks dpi by functionality that
they do not interfere with each other
2 and 7 cores are responsible for traffic transit and not very loaded.
To see the distribution of functions can be command:
ps -p `pidof fastdpi` H -o %cpu,lwp,psr,comm
```

2.Why DPI have not loaded the CPU core (12e not used core)?

```
In dpi there are service functions: netflow export, clickstream, pcap
export,
processing of control commands, and so on. Their load is uneven and they can
temporarily
load the core for 100%, so they are allocated on a separate core that they
do not interfere
with other funtionality for instance - transit
```

Дополнительная информация