

Table of Contents

Fixes in version 2.4 Polar Bear:

1. Bug fix: a mistake in subscriber's policing initialization may lead to a crash and restart of the main process.

[Update manual](#)

⚠ Do not update Linux kernel to the latest version kernel-2.6.32-431.29.2 or above. This kernel is not binary compatible with Kernel ABI. The network driver can not be loaded after this update. In case you made this update - please configure grub loader to load the previous version while solving the problem¹⁾.

Check what's new in [previous version](#).

¹⁾

Set the parameter default=1 in the file /etc/grub.conf