

# Table of Contents



1. The instruction "service fastdpi reload" does not work.
2. Utilities url2dic and ip2bin are absent.
3. The network driver can not be loaded after the kernel's update.